

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representative	es Present During the Inspection:
Company	Vicky Miller
OGM	Steve Demczak

Inspection Report

Permit Number:			
Inspection Type:			
Inspection Date:	Tuesday, January 18, 2011		
Start Date/Time:	1/18/2011 10:00:00 AM		
End Date/Time:	1/18/2011 4:00:00 PM		
Last Inspection:	Wednesday, December 14, 2011		

Inspector: Steve Demczak, Weather: 30's, Snow Covered InspectionID Report Number: 2619

Types of Operations

Accepted by: jhelfric

1/26/2011

Permitee: CANYON FUEL COMPANY Operator: CANYON FUEL COMPANY

Site: DUGOUT CANYON MINE

Address: PO BOX 1029, WELLINGTON UT 84542

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Total Permitted	9,751.00	
Total Disturbed	108.70	
Phase I		
Phase II		
Phase III		

Mineral Ownership

•	
✓ Federal	✓ Underground
✓ State	Surface
☐ County	Loadout
✓ Fee	Processing
Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There is one pending compliance action, NOV # 10072 issued on January 5th, 2011 for failing to prevent water pollution that resulted in the discharge of elevated levels of iron. The permittee is required to submit an abatement plan within 30 days of receipt of the NOV. The Permittee is current relative to the required electronic quarterly water monitoring submittals for 2010

Inspector's Signature:

Steve Demczak.

Wednesday, January 19, 2011 Date

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070039 Inspection Type: PARTIAL

Inspection Date: Tuesday, January 18, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		✓.	
3.	Topsoil	V		✓	
4.a	Hydrologic Balance: Diversions	✓		~	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		~	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.k	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	~		~	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070039 Inspection Type: PARTIAL

Inspection Date: Tuesday, January 18, 2011

Page 3 of 3

2. Signs and Markers

The permit sign is located at the gate to the property. Information meets the minimium requirements of the R645 Coal Rules.

3. Topsoil

There was no signs of wind or water erosion to the topsoil piles. Vegetation was growing on the topsoil piles.

4.a Hydrologic Balance: Diversions

Diversions are snow covered.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Sediment pond was inspected with no hazardous condition noticed during the inspection. Sediment pond did contain water but was not discharging during the inspection.

4.d Hydrologic Balance: Water Monitoring

I watched the permittee taking water sample at Pace Canyon. The permittee stated the water samples taken were around the 1.3 mg/l level.

8. Noncoal Waste

The site was clear of non-coal waste material.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

18. Support Facilities, Utility Installations

No new support facilities were constructed since the last inspection.